

November 30, 2023

Enforcement File: 2022 - 0154

Enercapita Energy Ltd.  
600, 215 2nd Street  
Calgary, AB T2P 1M4

Attention: Patrick Corbiell,

**RE: Warning: Fail to comply with Drilling and Production Regulation, B.C. Reg. 282/2010, Section 41.1.**

Dear Patrick Corbiell,

Enercapita Energy Ltd. is the operator and permit holder for numerous wells and facilities, at or near Fort St John British Columbia (BC). Permit holders who operate wells and facilities in BC have been required to complete surveys of wells and facilities since leak detection and repair (LDAR) requirements within the Drilling and Production Regulation (DPR) came into effect on January 1, 2020. The specific legislation that compels a permit holder to conduct surveys is contained in Section 41.1 of the DPR.

An evaluation of Enercapita Energy Ltd. survey data for wells and facilities for the calendar years 2021 and 2022 indicates that Enercapita Energy Ltd. failed to fully comply with section 41.1 of the DPR.

Given the circumstances, Enercapita Energy Ltd. is hereby issued a warning only for the following:

Enercapita Energy Ltd., between January 1, 2021 and December 31, 2021, at or near Fort St. John, in the Province of BC, did fail to complete all the required surveys for both wells and facilities contrary to section 41.1 of the DPR.

If Enercapita Energy Ltd. has any questions about this matter, please feel free to contact the undersigned.

Sincerely,

<original signed by>

Compliance and Enforcement Officer  
British Columbia Energy Regulator