

Date: February 7th, 2019

Canadian Natural Resources Ltd Suite 2500, 855- 2<sup>nd</sup> Street SW Calgary, AB T2P 4J8

Attention: Cindy Grieder, Lead Reclamation

Re: Canadian Natural Resources Certificate of Restoration Application (part II) for the Well Site CNRL Kahntah C-40-H/94-H-15 (WA # 15188)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 15188) submitted by SynergyAspen Environmental on behalf of Canadian Natural Resources Limited on December 19<sup>th</sup>, 2018.

Based upon review of the information provided by the applicant, the reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5959).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Canadian Natural Resources Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

CC:

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Operational Policy & Environment

Resource Development & Stewardship Branch

Telephone: 250-794-5234 Facsimile: 250-794-5390

E-Mail: Taher.Morsi@bcogc.ca


Adrian Renneberg, Synergy Environmental Strategies Inc, 9904 106 Street, Fort

St John, BC, V1J 1V8



## CERTIFICATION OF RESTORATION **APPLICATION FORM - PART 2**

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature. **COMMISSION USE ONLY** A Commission File No. or AD No.: Document: В **ADMINISTRATION** Well Permit No.: 15188 Well Name: CNRL KAHNTAH C- 040-H/094-H-15 Well Location: C- 040-H/094-H-15 Petroleum Title (Permit, Lease, Number, etc): 15188 Title Holder(s) (Permittee, Lessee, etc): Canadian Natural Resources Ltd. Surface Landowner: Crown Land Surface Occupant: N/A (Attach Letter of Release) NA (Attach Letter of Release) Applicant's Agent in Field: Name: Adrian Renneberg Company: SynergyAspen Environmental Inc. Position: Environmental Client Manager Address: 9904 106 Street City: Fort St. John Province: BC Postal Code: V1J 1V8 Phone: 250-785-1030 Fax: 250-785-1034 Email: arenneberg@synergyaspen.ca Agent Signature: Date: 10/18 \$1500 Application Fee Attached **RESTORATION INFORMATION** C Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The wellsite measured 120 m x 120 m and was constructed on forested, Crown land. The wellsite was accessed via an undisturbed 10 m x 183 m winter access road connecting to an existing 5 m trail and existing seismic line. No soil disturbance occurred on the winter access road. No ancillary sites were associated with the well location. The wellsite was located out of the boundaries of the Agricultural Land Reserve. It is the opinion of SynergyAspen Environmental Inc. that the wellsite and associated access road have been satisfactorily restored and no further work is required. Details of any areas left unrestored at Landowner's request: Crown Land Was "Approval to Construct" subject to any reclamation conditions?

Updated: 23-June-2016 Effective: 23-June-2016

Reclamation Inspection Report included?

Is this location within the Agricultural Land Reserve? If YES, attach Schedule B

YES

APPROVAL - FOR COMMISSION USE ONLY			2 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4 (4	D	
CERTIFICATE OF RESTORATION		CERTIFICATE NO. 5		959	-
This is to certify that the surface of satisfactorily restored. Despite the investigation or remedial action upor restoration requirements for which Approval Date:	issuance of this Certificate on inspection of the site or the Applicant is subsequen	e, the Ministry of Environm file. Issuance of this certi	ent has the authority ficate does not relieve	to order further site	
		Authorized Com	mission Employee		

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016