

GENERAL ORDER 2024-0137-02
Section 38 *Energy Resource Activities Act*

Issued to:

Secure Energy Services Inc.
Brookfield Place
2300, 225 6 Ave SW
Calgary, AB T2P 1N2

Attention: Greg Filipchuk, VP, Operations

Order:

Pursuant to section 38(1)(c) of the *Energy Resource Activities Act* (the Act), I, Dax Bourke, order that Secure Energy Services Inc. (Secure) must:

1. Develop a report completed by a Qualified Professional that must, at a minimum, identify the potential sources and causes of odours during operations and maintenance activities from Secure's Facility ID #7796 (Facility), located at 16-05-079-14. The report must also:
 - a) Identify current mitigation measures in place and any recommended additional measures to mitigate the sources and causes of odours from the Facility.
 - b) Include a rationale where no mitigation measures are recommended.
 - c) Include a required inspection and maintenance plan for the mitigation measures identified in (a), where applicable; and
 - d) Include a proposed timeline for the implementation of additional mitigation measures identified in (a), where applicable.

Request:

Pursuant to section 38(1)(e) of the Act, the BC Energy Regulator (BCER) requests that Secure submit a copy of the report referred to in Item 1, no later than November 29, 2024, electronically to C&E@bc-er.ca.

Conditions:

A. This order shall remain in effect until amended or terminated in whole or in part by the BCER.



Dax Bourke
Executive Director, Compliance and Enforcement
BC Energy Regulator

DATED AT Fort St. John, in the Province of British Columbia, this 13th day of November, 2024.