

Date: May 20th, 2016

EnCana Corporation 150-9th Avenue SW, P.O. Box 2850 Calgary, AB T2P 2S5

Attention: Diana Dunn, Environmental Advisor

Re: EnCana Corporation Certificate of Restoration Application (Part-II) for the Well Site ECA ECOG Maxhamish D-42-C/94-O-11 (WA # 18796))

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite (Never drilled) for the above referenced well authorization (WA # 18796) submitted by Gemini Environmental Solutions Ltd on behalf of EnCana Corporation on April 20th 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5625).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore potential liability related residual contamination from the subject oil and gas activity remains the responsibility EnCana Corporation.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Telephone: 250-794-5234 Facsimile: 250-794-5380


E-Mail: Taher.Morsi@bcogc.ca

cc: Nicole Stark, Gemini Environmental Solutions Ltd, 10543 100 Street, Fort St John, BC, V1J 3Z4



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

Together as a member in good statisting min an organization oppositing and other organizations.							
COMMISSION USE ONLY A							
Commission File No.:	D	ocument:					
ADMINISTRATION							
Well Permit No.: 18796							
Well Name: ECA ECOG Maxhamish				Well Location: d-42-C/94-O-11			
Petroleum Title (Permit, Lease, Number, etc):							
Title Holder(s) (Permittee, Lesse	ee, etc): Encana	Corporation					
Surface Landowner: Crown				Surface Occupant:			
(Attach Letter of Release)				(Attach Letter of Release)			
Applicant's Agent in Field							
Name: Nicole Stark							
Company: Gemini Environmental Solutions Ltd.				Position Team Lead, Reclamation and Remediation			
Address: 10543 100 St.	City: Fort St. John		n	Province: BC	=		
Postal Code: V1J 3Z4 Phone: 250.26		3.9155 Fa		ax: 250.263.9156	Email: nstark@geminicorp.ca		
Agent Signature: Date: April 14, 2016 2398 Nicole Stark PAg. OF AGRO Date: April 14, 2016							
\$1500 Application Fee Attached RESTORATION INFORMATION C							
RESTORATION INFORMATION							
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location): The wellsite, primary campsite and secondary campsite have been fully restored. The primary remote sump was not constructed. The secondary remote sump was unlikely to have been used with this wellsite (see the Reclamation Inspection report for further clarifications).							
	4						
Details of any areas left unrestored at Landowner's request:							

Updated: 20 January 2014 Effective: 6 February 2014

Was "Approval to Construct" subject to any reclamation conditions?							
Reclamation Inspection Report included?							
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B	□YES ⊠NO						
APPROVAL – FOR COMMISSION USE ONLY D							
CERTIFICATE OF RESTORATION CERTIFICATE NO. 5625							
This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.							
Approval Date: May 20th 2016 Authorized Commission Employee							
The personal information requested on this form is collected under the authority of and used for the purpose of administering the <i>Petroleum and Natural Gas Act and the Environmental Management Act.</i> Under certain circumstances, some information may be released subject to the provisions of the <i>Freedom of Information and Protection of Privacy Act.</i> If you have any questions about the collection, use or disclosure of this information, contact the							
Corporate Services Branch Decords Administrator in Fort St. John at the address above							

Updated: 20 January 2014 Effective: 6 February 2014