

Date: June 13th, 2016

Black Swan Energy Ltd
Suite 1200, 255-5th Ave S.W.
Calgary, AB
T2P 3G6

Attention: Bryan Lang

Re: Black Swan Energy Certificate of Restoration Application (Part-II) for the Well Site Black Swan Laprise D-66-A/94-G-8 (WA # 24181)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for the wellsite (**Never Drilled**) for the above referenced well authorization (WA # 24181) submitted by Highmark Environmental Services Ltd on behalf of Black Swan Energy Ltd on May 27th, 2016.

The reclamation inspection assessment report was reviewed and was found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5628).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."


And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Black Swan Energy Ltd remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

A handwritten signature in black ink, appearing to read 'Taher Morsi'. The signature is written in a cursive style with a horizontal line above the first part of the name.

Taher Morsi, Ph.D., P.Ag
Environmental Management Officer
Telephone: 250-794-5234
Facsimile: 250-794-5380

E-Mail: Taher.Morsi@bcogc.ca

cc: Chris Weissbach, Highmark Environmental Services Ltd, SS2 Site 12 Comp 101,
St. John, BC, V1J 4M7




**CERTIFICATION OF RESTORATION
APPLICATION FORM – PART 2**
Physical Address: 6534 Airport Road,
Fort St. John, B.C. V1J 4M6
Mailing Address: Bag 2, Fort St. John, B.C.
V1J 2B0
Phone: (250) 794-5200

RECEIVED
MAY 27 2016
BC Oil and Gas Commission
Date Received

THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.


COMMISSION USE ONLY			A
Commission File No.: 9629380		Document:	
ADMINISTRATION			B
Well Permit No.: 24181			
Well Name: Black Swan Lapise		Well Location: d-066-A/094-G-08	
Petroleum Title (Permit, Lease, Number, etc):			
Title Holder(s) (Permittee, Lessee, etc) Black Swan Energy Ltd.			
Surface Landowner: BC CROWN <i>(Attach Letter of Release)</i>		Surface Occupant: <i>(Attach Letter of Release)</i>	
Applicant's Agent in Field			
Name: Chris Weissbach			
Company: Highmark Environmental Services Ltd.		Position: Owner	
Address: 10121 95 th Ave.		City: Fort St. John	Province: BC
Postal Code: V1J 1H9	Phone: 250-261-6994	Fax: 250-261-6928	Email: Chrisw@hesl.ca
Agent Signature:		Date: May 12, 2016	
<input checked="" type="checkbox"/> \$1500 Application Fee Attached			
RESTORATION INFORMATION			C
Description of Area(s) Restored (Location, Remote Sump, Access and other disturbed areas affiliated with this location):			
Wellsite: 125 m x 120 m and Winter Access: 1055 m x 20 m			
Details of any areas left unrestored at Landowner's request:			
N/A			
Was "Approval to Construct" subject to any reclamation conditions?			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Reclamation Inspection Report included?			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B			<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO



CERTIFICATE OF RESTORATION

CERTIFICATE NO. 5628

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date: June 13, 2016

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act* and the *Environmental Management Act*. Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act*. If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.