

Date: August 28th, 2018

Sinopec Daylight Energy Ltd Suite 2700, 112- 4th Avenue SW Calgary, AB T2P 0H3

Attention: Jeff Wilton, Construction & Environment

Re: <u>Sinopec Daylight Energy Certificate of Restoration Application (part II) for the</u> Well Site SDEL Et Al Martin C-2-F/94-H-6 (WA # 14835)

This office has received an Application for a Certificate of Restoration (CoR-Part II), and a Surface Reclamation Assessment Report for wellsite for the above referenced well authorization (WA # 14835) submitted by Applied Environmental Consulting Ltd on behalf of Sinopec Daylight Energy Limited on August 27th, 2018.

The reclamation assessment report reviewed and found that the site has been fully reclaimed and the restoration of the site is satisfactory. Therefore, your application for a Certificate of Restoration is approved and a copy of the Certificate of Restoration is enclosed (Certificate # 5878).

Please note Section 41(3) of the Oil and Gas Activities Act (OGAA) and section 47 (1) of the Environmental Management Act, which respectively read:

"The issuance of a certificate of restoration does not relieve a person from any obligations under section 40 or under an order referred to in subsection (1) (b) of this section in respect of any matter that was not known to the commission at the time the certificate of restoration was issued."

And:

"A person who is responsible for remediation of a contaminated site is absolutely, retroactively and jointly and separately liable to any person or government body for reasonably incurred costs of remediation of the contaminated site, whether incurred on or off the contaminated site."

Therefore Sinopec Daylight Energy Limited remains liable for any contamination presently on site.

Any questions can be directed to the undersigned at (250) 794-5234

Sincerely,

Taher Morsi, Ph.D., P.Ag

Environmental Management Officer

Resource Development & Stewardship Branch

Operational Policy & Environment

Telephone: 250-794-5234 Facsimile: 250-794-5380

E-Mail: Taher.Morsi@gov.bc.ca

cc: Robert Halstead, Applied Environmental Consulting Ltd, 976 East Chestermere Dr., Chestermere, AB T1X 1R2



CERTIFICATION OF RESTORATION APPLICATION FORM – PART 2

Physical Address: 6534 Airport Road, Fort St. John, B.C. V1J 4M6 Mailing Address: Bag 2, Fort St. John, B.C. V1J 2B0 Phone: (250) 794-5200



THIS IS AN AUDITABLE DOCUMENT

This form must be submitted under the authorities of the Oil and Gas Activities Act, s. 41, and the Environmental Management Act S.B.C. 2003, c. 53, in hardcopy, to the Oil and Gas Commission, at the address noted above. This form may only be completed by a professional or technologist registered as a member in good standing with an organization operating under an act of the British Columbia legislature.

		COMMISSIO	ON U	JSE ONLY		A Commence of the Commence of	
Commission File No. or AD No.:	:	A 337-100-2-3-3-7-14-6-1	I	Document:			
		ADMINIS	STRA	ATION			
Well Permit No.: WA014835						KHI W	
Well Name: Midnight Martin				Well Location: c-2-F/94-	H-6		
Petroleum Title (Permit, Lease,	Number, etc): (OGC File #96090	029,	OGC License #904848			
Title Holder(s) (Permittee, Lesse	e, etc): Sinope	ec Daylight Energ	gy Lto	d.			
Surface Landowner: Crown				Surface Occupant: None			
(Attach Letter of Release) Applicant's Agent in Field: Robert Halstead				(Attach Letter of Release)			
Name: Jeff Wilton	Jen Haisteau						
Company: Sinopec Daylight Energy Ltd.				Position: Manager, Construction and Environment			
Address: 2700, 112-4 th Ave. SW		City: Calgary	Т		Province: Alberta		
Postal Code: T2P 3H0	Phone: 403-23	32-4224	Fax	x: 403-266-6988 Email: jeff.wilton@sinopeccanada.con			
Agent Signature:					Date: 2/8-06-	-15	
\$1500 Application Fee Att	ached						
		RESTORATION	N INF	FORMATION		C	
Description of Area(s) Restored	(Location, Remot	e Sump, Access a	and oth	her disturbed areas affiliated	with this location):		
Wellsite, access road and camp	site			XI.			
d							
Details of any areas left unrestor	red at Landown	er's request:					
None		and the second s					

			-			3	
Was "Annroyal to Construct" sub	niect to any recl	amation condition	ns?			TYES NO	
Was "Approval to Construct" subject to any reclamation conditions? Reclamation Inspection Report included?							
		0.161/20	1-0	Defendade D			
Is this location within the Agricultural Land Reserve? If YES, attach Schedule B							

Updated: 23-June-2016 Effective: 23-June-2016

				SE ONLY

5878

D

CERTIFICATE OF RESTORATION

CERTIFICATE NO.

This is to certify that the surface of the land held in conjunction with, or incidental to, the above application is deemed to be satisfactorily restored. Despite the issuance of this Certificate, the Ministry of Environment has the authority to order further site investigation or remedial action upon inspection of the site or file. Issuance of this certificate does not relieve the Applicant of any restoration requirements for which the Applicant is subsequently held responsible by the Commission.

Approval Date:

Angust 28, 2018

Authorized Commission Employee

The personal information requested on this form is collected under the authority of and used for the purpose of administering the *Petroleum and Natural Gas Act and the Environmental Management Act.* Under certain circumstances, some information may be released subject to the provisions of the *Freedom of Information and Protection of Privacy Act.* If you have any questions about the collection, use or disclosure of this information, contact the Corporate Services Branch, Records Administrator, in Fort St. John at the address above.

Updated: 23-June-2016 Effective: 23-June-2016